



Product Safety Recall

Do you own this product?

Telescopic Magnetic Pick-up Tool with LED

Telescopic magnetic pick-up tool with LED sold as part of the WORKZONE® PICKUP TOOL 2 PIECE PACK. Product code 815174.

Dates sold: 26/11/2022 – 19/04/2023



Why the product is recalled: The product does not comply with [the mandatory safety standard for products containing button/coin batteries](#). The battery compartment is not adequately secured so button batteries may be accessible.

Hazard: There is a risk of choking, severe internal burn injuries or death to young children if they gain access to the button batteries and ingest them.



1. Consumers should immediately stop using the pick-up tool and store it out of reach of children, then return it to any Aldi store for a full refund.
2. Send us an email or phone us if you are unable to return the product or have sold or gifted it to another person



- For more information, contact ALDI stores on customerservice@aldi.com.au,
- or recall helpline on 13 25 34 (Monday to Friday, 8.30am - 5.30pm AEST)
- or visit <https://www.aldi.com.au/en/about-aldi/product-recalls/>



Purchased from: Aldi Stores

PRA2023/19811

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information